

Technical Service Information

THM 3T40 (125C) RAISE CONVERTER CLUTCH APPLY SPEED

COMPLAINT: Torque Converter Clutch applies at too low vehicle speed, on computer controlled vehicles

only.

CAUSE: Computer Calibration.

CORRECTION: There is now available from most aftermarket sources, a two prong, normally open (NO)

switch, that completes from terminal to terminal when it closes, and it closes at 40-45 PSI (See Figure 1). This switch when installed in the governor pressure port, in series with the "D" wire (Computer Ground Signal), will raise the lock-up speed to approximately 45 MPH, and you will still have capability to release TCC with the throttle position sensor. We have shown it here in a 125C (See Figure 21, both internal and external application, but it

can be used in any G.M. vehicle that gives you access to governor pressure.

CHECK WITH YOUR LOCAL SUPPLIER FOR PARTNUMBER




Figure 1



Technical Service Information

