

Technical Service Information

FORD E4OD CONVERTER CLUTCH SHUTTER

COMPLAINT: Soft converter clutch engagement or shudder on hard acceleration

CAUSE: Low converter pressure and/or limited ability of the converter exhaust orifice to control

converter clutch apply.

CORRECTION: Replace the converter regulator valve spring in the pump cover with a "SGSF E40D" shudder fix spring (see figure 1), Drill the converter clutch exhaust orifice to .076 in. (see figure 1).




Figure 1



Technical Service Information




Figure 2 Figure 3




Figure 4