


## **Technical Service Information**

## THM 440-T4 UPPER CHANNEL PLATE GASKET CONNECTED

There has been a new Upper Channel Plate Gasket released that connects the modulator port gasket and upper channel plate gasket together. This change was implemented to help prevent misassembly of the gaskets during the assembly process (See Figure 1).

The new upper channel plate gasket will retro fit back to 85 1/2 hydraulics only, because of the absence of one dam in the gasket. The previous design gaskets may still be used.

SPECIAL NOTE: DO NOT USE THE NEW GASKET ON 1985 HYDRAULICS.



DO NOT USE ON 1985 HYDRAULICS TRANSAXLES

Copyright © 2001 ATSG

Figure 1

88-37 Page 1 of 1