

Technical Service Information

CHRYSLER A604 SELECTOR LEVER HARD TO MOVE

COMPLAINT: Vehicles equipped with A604 transmissions may exhibit trouble moving the selector lever

into any range.

CAUSE: The cause may be, a bad Neutral Safety or PRNDL switch, a binding Manual shaft or a bad

shifter cable

CORRECTION: Disconnect the shifter cable from manual shaft lever shown in Figure 1. Rotate the manual shaft lever through all ranges. If the lever rotates freely, replace the shifter cable. If the lever is still hard to move, loosen or remove the Neutral Safety and/or PRNDL switch and rotate the manual shaft lever. If the lever rotates freely, replace the Neutral Safety and/or PRNDL switch. If the lever is still hard to move, remove the valve body and inspect the manual shaft for straightness and remove any corrosion or rust from the shaft.

SERVICE INFORMATION:

SAFETY NEUTRAL SWITCH	4671017
PRNDL SWITCH	4671019

