


Technical Service Information

THM 3L80 (400) VALVE BODY GASKET CHANGE

Beginning November 23, 1987, all TH400 transmissions were built, with new valve body gaskets. (SEE BELOW) This change and additional changes done to the case, valve body, and separator plate, were done to relieve a harsh park/neutral to reverse engagement shift feel.



8670447
SEE BULLETIN 88-33 FOR CASE AND SEPARATOR PLATE DIFFERENCES.

Copyright © 2000 ATSG

Figure 1