

# **Technical Service Information**

# FORD E4OD/4R100 NEW DESIGN 6 PINION FORWARD AND REVERSE PLANETARY CARRIER

**CHANGE:** Beginning at the start of production for all 1998 model E4OD transmissions, *some models* will be equipped with a new design 6 pinion forward planetary carrier (See Figure 1), and a new design 6 pinion reverse planetary carrier (See Figure 2).

**REASON:** Increased torque carrying capacity and increased planetary carrier durability.

### PARTS AFFECTED:

- (1) FORWARD PLANETARY CARRIER Now has 6 pinions instead of the previous 4 pinions for increased torque carrying capacity and increased durability (See Figure 1).
- (2) REVERSE PLANETARY CARRIER Now has 6 pinions instead of the previous 4 pinions for increased torque carrying capacity and increased durability (See Figure 2).

#### INTERCHANGEABILITY:

The new design forward planetary carrier *will back service all models* of the E4OD, but it *does require* the latest design forward ring gear hub and bearing assembly, as there are no holes for the previous design thrust washer (See Figure 1).

The new design reverse planetary carrier *will back service all models* of the E4OD, but it *does require* the latest design reverse clutch hub and three tang thrust washer for both sides, as shown in Figure 2.

#### **SERVICE INFORMATION:**

Forward Planetary Carrier (6 Pinion)	F81Z-7A398-CA
Reverse Planetary Carrier (6 Pinion)	F81Z-7D006-AA

Copyright © 1998 ATSG



# **Technical Service Information**





Figure 1




# **Technical Service Information**

### NEW DESIGN 6 PINION REVERSE PLANETARY CARRIER PART NUMBER F81Z-7D006-AA




Front View




Rear View

### **REQUIRES 1997-UP DESIGN LEVEL** REVERSE CLUTCH HUB ASSEMBLY



## **REQUIRES 3 TANG THRUST WASHERS** ON BOTH SIDES OF REAR CARRIER PART NUMBER F0TZ-7A166-D



Copyright © 1998 ATSG