

Technical Service Information

THM 4L60-E

NEW PARK/NEUTRAL BACK-UP FOR ALL 2004 MODELS

CHANGE: Beginning at the start of production for 2004 models, equipped with the THM 4L60-E

transmission, a revised Park/Neutral Back-Up (PNBU) switch was implemented with one 12 pin connector instead of the previous two connectors (See Figure 2). 2000-2003 models are shown

in Figure 3.

REASON: Improved reliability and durability.

PARTS AFFECTED:


- (1) PARK/NEUTRAL BACK-UP SWITCH Now has only one connector instead of the previous two connector switch, as shown in Figure 2.
- (2) PARK/NEUTRAL BACK-UP SWITCH CONNECTOR Revised vehicle harness connector to accommodate the revised PNBU Switch, as shown in Figure 2.

INTERCHANGEABILITY:

Will not interchange with any previous models.

SERVICE INFORMATION:

Park/Neutral Switch (1996-2003 Models)	29540479
Park/Neutral Switch (2004-Up Models)	24221125





Technical Service Information

2004 PARK/NEUTRAL BACK-UP SWITCH					
PIN	Wire Color	Circuit	Function		
1	Dk Green	1433	Clutch Start Switch		
2			Not Used		
3			Not Used		
4	Yellow	772	Transmission Range Switch "B"		
5	Black/White	771	Transmission Range Switch "A"		
6	Gray	773	Transmission Range Switch "C"		
7	Black/White	451	Ground		
8	White	776	Transmission Range Switch "P"		
9	Lt Green	275	Park/Neutral Position Switch Signal		
10	Gray	1524	Back-Up Lamp Supply Voltage		
11	Pink	839	Ignition 1 Voltage		
12	Purple	639	Ignition 1 Voltage		




Figure 2
AUTOMATIC TRANSMISSION SERVICE GROUP

04-40 Page 2 of 3



Technical Service Information




Figure 3
AUTOMATIC TRANSMISSION SERVICE GROUP

04-40 Page 3 of 3