

## **Technical Service Information**

## RE4RO1A REPEATED PLANETARY FAILURE

**COMPLAINT:** RE4R01A transmissions found in Nissan Pathfinders, 200SX, and 300ZX vehicles may

experience repeated planetary failure

CAUSE: Most Nissan vehicles have what is known as a "Fin Type" cooler. This type cooler

becomes easily restricted, causing poor cooler flow, and resulting in repeated planetary

failure. Cooler line flushing machines CANNOT flush clear this type of cooler.


**CORRECTION:** In the past the entire radiator needed to be replaced to update the cooling system. Nissan

has now made available, under OEM part number 21606-15V25, a spiral cooler replacement kit, so the entire radiator does not require replacement (See Figure 1).

## **SERVICE INFORMATION:**

Cooler Replacement Kit......21606-15V25

## SPIRAL COOLER REPLACEMENT KIT FROM NISSAN



**OEM PART NUMBER 21606-15V25** 

Copyright © 2001 ATSG

Figure 1

95-21 Page 1 of 1