


## **Technical Service Information**

## 61-65 LINCOLN CAST IRON TUBE IDENTIFICATION AND PLACEMENT



97-56 Page 1 of 1