

Technical Service Information

THM 3T40 (125C) NEW DESIGN FORWARD CLUTCH HOUSING AND WASHER

CHANGE: A new design forward clutch housing and thrust washer went into production on November

3, 1987, for all 1988 model 125C transaxles.

REASON: The new housing contains a new stamped channel which increases forward clutch feed oil,

providing a quicker neutral to drive engagement. (See Figure 1).

PARTS AFFECTED

(1) FORWARD CLUTCH HOUSING - Contains a stamped channel which increases the flow of forward clutch feed oil, and there is a revised dimension where the bronze washer is located (See Figure 1).

(2) BRONZE THRUST WASHER - Revised dimension on the inside diameter of washer to fit the new clutch housing, and identified with a dimple stamped on both sides of the washer (See Figure 1).

INTERCHANGEABILITY:

- (1) The new forward clutch housing will retro fit back to all previous models but you MUST use the 3rd design "Dimpled" washer.
- (2) The 1st design plastic washer, and the 2nd design bronze washer will not fit the new forward clutch housing.
- (3) If the 3rd design "Dimpled" bronze thrust washer is used on the previous forward clutch housing, it will create premature wear on the housing and Washer.

SERVICE INFORMATION:

Bronze Thrust Washer (2nd Design)	8652759
Bronze Thrust Washer (3rd Design "Dimpled")	
Forward Clutch Housing and Washer Kit (1988 Design)	



Technical Service Information




Figure 1