

# **Technical Service Information**

## THM 440-T4 HARSH 3-2 DOWNSHIFT AND/OR 4-2 DOWNSHIFT

**COMPLAINT:** A harsh 3-2 and/or 4-2 forced downshift condition at either full and/or part throttle, may occur

at high altitude (Above 4000 Feet) or at low altitude (Below 4000 Feet).

**CAUSE:** Original calibrations may need to be updated with a service 3-2 control valve spring per

customer's requirements.

**CORRECTION:** Replace the 3-2 control valve spring with the appropriate service part number as it is model

sensitive. Part numbers are as follows:

#### **SERVICE INFORMATION:**

#### HARSH 3-2 SHIFT - HIGH ALTITUDE ONLY.

2WWH
2YBH, 2YCH, 2YKH
2WFH
1WWH, 1WSH, 1WXH, 1PAH
IYDH, ICHH, IYHH, ICJH,
1YSH, 1CAH, 1YTH, 1CBH
IWMH, 1BHH
lWFH, lBDH, lBAH, lWDH,
lWJH, lBJH, lWPH, 1BWH
OPAH, OWXH
OAAH, OKCH, OABH, OKDH, OAFH,
OKPH, OANH, OKRH, OATH, OKLH,
OBFH, OWHH,i
OBHH, OWMH
OBAH, OWDH, OBDH, OWFH, OBWH,
OWPH, OBJH, OWJH, OCJH, OCHH
OLMH, OYSH, OLNH, OYTH,
OYKH, OYDH, OYLH, OYHH
OAJH, OKHH, OBPH, OWNH
9AAH, 9ABH, 9AFH, 9ANH,
9ATH, 9AJH
9BPH, 9WRH
9BHH, 9PAH, 9WBH, 9WCH
9BAH, 9BDH, 9BJH, 9BWH, 9YCH,
9YAH, 9YBH, 9YJH, 9YFH
9BFH, 9BMH, 9WUH, 9WZH, 9VYH
9CDH, 9CLH, 9CPH, 9CYH, 9CZH
9PBH, BWLH, 9WKH
9ACH, 9ADH, 9AHH



## **Technical Service Information**

HARSH 3-2 SHIFT - HIGH ALTITUDE ONLY.	
8FCH	8646979
8BKH, 8FBH	
8BJH, 8BRH, 8BTH, 8BYH, 8FJH	
7FCH, 7FZH	
7FBH, 7FKH	
7FJH, 7FNH, 7FRH, 7FTH	
6BCH, GBDH, GBMH, GBZH,	
GFCH, 6FZH	8646979
6BAH,	
GACH, 6AWH	
f5m, GAMH, GAFH, GAPH, GASH,	
6AYH, GBBH, GBHH, 6FBH	8646982
GCMH, GCNH, 6CFH	
GBLH, 6BTH, 6BYH	
GFTH, 6FYH	
5BX	
5AC, 5AY, 5BW	
5AM	
5CM, 5CN	
5BR, 5CP, 5CW	
5BV	
HARSH 3-2 SHIFT - LOW ALTITUDE ONLY	9646070
2YBH, 2YCH, 2YKH	
2YBH, 2YCH, 2YKH 2WFH	8646993
2YBH, 2YCH, 2YKH 2WFH 2WwH	8646993
2YBH, 2YCH, 2YKH 2WFH 2WwH IYDH, ICHH, IYHH, ICJH, IYSH,	8646993 8662907
2YBH, 2YCH, 2YKH 2WFH 2WwH 1YDH, ICHH, IYHH, ICJH, IYSH, ICAH, IYTH, 1CBH	8646993 8662907 8646979
2YBH, 2YCH, 2YKH	8646993 8662907 8646979
2YBH, 2YCH, 2YKH	8646993 8662907 8646979 8646980
2YBH, 2YCH, 2YKH	8646993 8662907 8646979 8646980 8646993
2YBH, 2YCH, 2YKH	8646993 8662907 8646979 8646980 8646993 8662907
2YBH, 2YCH, 2YKH	8646993 8662907 8646979 8646980 8646993 8662907
2YBH, 2YCH, 2YKH	8646993 8662907 8646979 8646980 8646993 8662907
2YBH, 2YCH, 2YKH	8646993 8662907 8646979 8646980 8646993 8662907 8646979
2YBH, 2YCH, 2YKH	8646993 8662907 8646979 8646980 8646997 8646979
2YBH, 2YCH, 2YKH	8646993 8662907 8646979 8646980 8646997 8646979
2YBH, 2YCH, 2YKH	8646993 8662907 8646979 8646980 8646993 8646979 8646980 8646981
2YBH, 2YCH, 2YKH	8646993 8662907 8646979 8646980 86469979 8646980 8646981 8646993
2YBH, 2YCH, 2YKH	8646993 8662907 8646979 8646980 8646997 8646979 8646981 8646993 8662907
2YBH, 2YCH, 2YKH 2WFH	8646993 8662907 8646979 8646980 8646997 8646979 8646981 8646993 8662907 8662932
2YBH, 2YCH, 2YKH	8646993 8662907 8646979 8646980 8646997 8646979 8646981 8646993 8662907 8662932 8675962



## **Technical Service Information**

### HARSH 3-2 SHIFT - LOW ALTITUDE ONLY 9AAH, 9ABH, 9AFH, 9AJH, 9ANH, 9ATH, 9WTH ......8646953 9BFH, 9BMH, 9WUH, 9WZH, 9VYH ....... 8646980 9BAH, 9BDH, 9BJH, 9BWH, 9YAH, 9YBH, 9YJH, 9YFH, 9YCH .......8646981 9BCH, 9BHH, 9PAH, 9WBH .......8646993 9ACH, 9ADH, 9AHH ...... 8675936 6BAH, GBLH, GBTH, GBYH, GFTH, 6FYH ...... 8646979 GCNH, 6CMH, 6CFH ...... 8646994