

Technical Service Information

ACURA 4 SPEED HYDRAULIC NO REVERSE

COMPLAINT: No reverse.

CAUSE: Missing governor feed pipe.

CORRECTION:Replace feed pipe.




Figure 1

Copyright © 2000 ATSG