

Technical Service Information

FORD AX4S (AXOD-E) AND AX4N PRESSURE TAP LOCATIONS

Most technical manuals, including Ford Motor Company manuals, have the pressure tap locations identified wrong. Use the next two pages to correct your manuals at the shop for the correct pressure tap locations.

Refer to Figure 1 for the AX4S (AXOD-E) transaxle pressure tap locations.

Refer to Figure 2 for the AX4N transaxle pressure tap locations.



Technical Service Information




Figure 1
AUTOMATIC TRANSMISSION SERVICE GROUP



Technical Service Information




Figure 2
AUTOMATIC TRANSMISSION SERVICE GROUP