

## **Technical Service Information**

## THM 440-T4 NEW 4TH CLUTCH STEEL PLATES

**CHANGE:** New 4th clutch steel plates with "Blackened" edges (See Figure 1).

**REASON:** The new plates are made with a new process, to aid manufacturing. The by-product of this

new process is that the edges will be blackened, and the clutch surfaces will have some lightly

blackened areas.

## **PARTS AFFECTED:**

(1) 4TH CLUTCH STEEL PLATES - Will have "Blackened" edges and the clutch surfaces will have some lightly blackened areas (See Figure 1). Do not replace the steel plates merely for this condition, as it is normal.

## **INTERCHANGEABILITY:**

The new "Blackened" 4th clutch steel plates will retro-fit back to ALL previous models. When the supply of previous steel plates is depleted,

the blackened plate will be the only one available through OEM sources.




Figure 1