


## **Technical Service Information**

## THM 4L60-E DELAYED ENGAGEMENT IN DRIVE AND/OR REVERSE

**NEVER RE-USE CASTING NUMBER 8681725Z** 

ALWAYS REPLACE THE LO/REVERSE PISTON WITH CASTING NUMBER 86855501 OEM PART NUMBER FOR THE NEW L/R PISTON IS 8685549




94-02 Page 1 of 1



## **Technical Service Information**

## **4L60-E SPACER PLATE**



- 49 SPACER PLATE SCREEN SNAPS INTO PLATE FROM CASE SIDE.
- 50 SPACER PLATE SCREEN SNAPS INTO PLATE FROM CASE SIDE.
- 51 SPACER PLATE SCREEN SNAPS INTO PLATE FROM V.B. SIDE (NOT USED ALL MODELS).

FOR A DELAY FORWARD DRILL HOLE "B" OUT TO .125" DIAMETER.

FOR A DELAY TO REVERSE DRILL HOLE "C" OUT TO .125" DIAMETER.