

FORD 4R70E/4R75E CHANGES FOR 2004

CHANGE: Beginning at the start of production for 2004, Ford Motor Company introduced a new rear drive transmission with the designation 4R70E or 4R75E, which is based on the 4R70W. This transmission now has a redesigned Pump and Stator assembly, Intermediate Clutch assembly, Forward Drum, Sun Gear Shell, Center Support, Anti-Rattle Clip, an added Turbine Speed Sensor, a redesigned transmission case, a shorter Output Speed Sensor and a redesigned Ring gear.

REASON: Improved up-shift and downshift timing and better gear calculation and for ease of assembly.

PARTS AFFECTED:

- (1) INTERMEDIATE CLUTCH PISTON AND PUMP BODY The Intermediate Clutch Piston was changed form the previous design Aluminum piston with individual lip seals, as shown in Figure 1, to a stamped steel bonded rubber piston as shown in Figure 2. Along with this change, the Pump Body was redesigned to accommodate the new larger piston and the elimination of the Spring Retainer. A new return spring and retainer was added into the case as shown in Figures 3 and 4.
- (2) PUMP STATOR The Pump Stator Forward Clutch sealing ring groove depth changed to accommodate a new Plastic Butt Cut Sealing Ring as shown in Figure 5.
- (3) FORWARD DRUM The Forward Drum had a stamping change to provide projections for the added Turbine Shaft Speed Sensor, as shown in Figure 6, and Forward feed was changed.
- (4) SUN SHELL-The Sun shell can be easily identified by the new rivets that retain the shell to the Sun Gear as shown in Figure 7. The new shell is manufactured from a non-ferrous metal which will not attract a magnet, so the added turbine sensor can read the Forward Clutch Drum. *NOTE: 2005 models do not have the rivets for identification and will retrofit to 2004 models.*
- (5) CENTER SUPPORT The new design Center Support has a notch cut out of it to accommodate the added Turbine Sensor, as shown in Figure 8. A new design Anti-rattle Clip was also added for ease of assembly, which was changed in the 2002 model year.
- (6) TRANSMISSION MAIN CASE The case was changed to accommodate the added turbine sensor as shown in Figure 9.
- (7) REAR INTERNAL RING GEAR Now manufactured with extended parking lugs on the ring gear to trigger the New *Shorter* Output Speed Sensor, instead of the previous design holes in the center of the ring gear as shown in Figure 10.

INTERCHANGEABILITY:

None of the parts listed above will interchange with the previous design 4R70W parts.

SERVICE INFORMATION:

INTERMEDIATE CLUTCH BONDED PISTON	3L3Z-7E005-AA
FORWARD CLUTCH PLASTIC SEALING RINGS (2)	3L3Z-7D019-AA
FORWARD CLUTCH DRUM	3L3Z-7F207-AA
SUN GEAR SHELL	5L3Z-7A019-AB
TURBINE SHAFT SPEED SENSOR	3L3Z-7M101-AA
OUTPUT SHAFT SPEED SENSOR	3L3Z-7H103-AA

07-05 Page 1 of 10






Figure 1







Figure 2



PREVIOUS DESIGN PUMP AND INTERMEDIATE CLUTCH PISTON CROSS-SECTION



NEW DESIGN PUMP AND INTERMEDIATE CLUTCH PISTON CROSS-SECTION




Figure 3







Figure 4



PUMP STATOR PREVIOUS DESIGN NEW DESIGN RING GROOVE RING GROOVE DEPTH .100" DEPTH .072" 00 00 00 **SEALING RING SEALING RING** WIDTH .110" WIDTH .083" LATCH TYPE STEEL **BUTT CUT PLASTIC SEALING RINGS SEALING RINGS** Copyright © 2006 ATSG











Figure 7



CENTER SUPPORT



PREVIOUS DESIGN
Anti-Clunk Spring



NEW DESIGN Anti-Clunk Spring



NOTE: The anti-clunk spring was changed in the 2002 model year. Ford part number 2L3Z-7F277-AA

Copyright © 2006 ATSG

Figure 8






Figure 9




Figure 10