

Technical Service Information

FORD E4OD NEW DESIGN INTERMEDIATE SERVO PISTON ASSEMBLY

CHANGE: Beginning on August 8, 1995, all 1996 model E40D transmissions were produced with a new design Intermediate Band Apply Servo Assembly (See Figure 1).

REASON: Ease of installation on the assembly line.

PARTS AFFECTED:

- (1) **INTERMEDIATE SERVO PISTON** Total change in design, as shown in Figure 1.
- (2) **SERVO PISTON RETAINER** Eliminated, as shown in Figure 1.
- (3) **RETAINING SNAP RING** Eliminated, as shown in Figure 1.
- (4) **TRANSMISSION CASE** Snap ring groove in the case piston bore was eliminated, as it was no longer need (See Figure 2).

INTERCHANGEABILITY:

- (1) When replacing the Intermediate Band Apply Servo Assembly becomes necessary, either design level (Previous or New) can be used in a previous model transmission case, as the new design level part will retro-fit back to all previous model units.
- (2) When using the new design piston and seal assembly in a previous model transmission, discard the piston retainer and the snap ring.
- (3) If you have the later model transmission without the snap ring groove in the piston bore, on & the new design piston and seal assembly can be used.

SERVICE INFORMATION:

Copyright © 2000 ATSG



Technical Service Information




Figure 1



Technical Service Information




Figure 2
AUTOMATIC TRANSMISSION SERVICE GROUP