

Technical Service Information

FORD E4OD FORWARD CLUTCH RETURN SPRING

COMPLAINT: Forward clutch piston return spring fatigued, worn, and/or broken.

CAUSE: Improper orientation of steel ring on top of the forward clutch piston, and the forward clutch

piston return spring.

CORRECTION: Position the forward clutch piston return spring so that both ends of the steel ring are visible within the space between the two adjacent fingers of the return spacing as shown in Figure 1.

