

## **Technical Service Information**

## THM 440-T4 SPACER PLATE I.D. (3-2 LINE CONTROL)

CHANGE: A 4th design Reverse Band Assembly is now in production on all THM 440-T4

transaxles.

**REASON:** To help eliminate a harsh reverse apply condition.

PARTS AFFECTED: (1) REVERSE BAND ASSEMBLY -been changed, The lining on the reverse band has

once again and can be identified by the "Paper" lining on the band itself (See Figure 1).

## **INTERCHANGEABILITY:**

It will retro-fit back to all previous models and is highly recommended to help eliminate

a harsh reverse apply condition.

## **SERVICE INFORMATION:**




Figure 1