

# **Technical Service Information**

### FORD E40D

### ADDED LUBE ORIFICE PLUG FOR SOME 1997 MODELS

**CHANGE:** Beginning on 7/24/97, a new design transmission case and extension housing were released for production for 1997 model Econoline, Expedition, F Super Duty, F150-350 Series Trucks and 1998 Navigator vehicles. (See Figures 1 and 2).

**REASON:** Improved lubrication distribution to extension housing bushing.

#### PARTS AFFECTED:

- (1) TRANSMISSION CASE Added passage at the rear of transmission case to accept the added plastic lube orifice plug, as shown in Figure 1.
- (2) EXTENSION HOUSING Added cast-in shoulder/boss that retains the added lube orifice plug in the transmission case, as shown in Figure 2.

#### **INTERCHANGEABILITY: (97-23-13**

- (1) The new design extension housing *with* the added cast-in shoulder or boss will service *any* E4OD transmission case, past or present (See Figure 2).
- (2) The previous design extension housing *without* the cast-in shoulder or boss can only be used on transmission cases built prior to 7/24/97 not having the lube orifice plug (See Figure 2).

#### **SERVICE INFORMATION:**

Extension Housing, 5.4L, 6.8L, 7.3L, 2 Wheel Drive	F85Z-7A039-DA
Extension Housing, 4 Wheel Drive	F7TZ-7A039-AA
Extension Housing, Super Duty	F7UZ-7A039-BA
Transmission Case, 5.4L, 6.8L	F75Z-7005-BB
Transmission Case, 7.3L	F7UZ-7005-BA
Lube Orifice Plug, All	. F81Z-7E380-AA

Copyright © 1998 ATSG



# **Technical Service Information**





Figure 1



## **Technical Service Information**






Figure 2