

#### FORD F4E-III VALVE BODY CHANGES

**CHANGE:** Beginning at the start of production for the 1998 model year, Escort and Tracer vehicles equipped with the new F4E-III transaxle recieved a totally new valve body assembly, with many engineering changes that will affect service.

**REASON:** Improved line pressure and torque converter clutch control.

#### PARTS AFFECTED:

• The pressure control solenoid, solenoid body, spacer plate and gaskets were changed. The pressure modifier valve was also changed and a spring was added to the end of the valve and an adjustable bore plug replaced the old retainer. Refer to Figure 1 for the previous design parts and Figure 2 for the new design parts as well as the new pressure modifier valve line-up.

The main valve body upper side was changed to accomodate the new pressure control solenoid

• body and spacer plate. Refer to Figure 3.

The main valve body lower side was changed to incorperate a new solenoid reducing valve.

• See Figure 4 for the previous design and Figure 5 for the new design.

The main valve body spacer plate and gaskets were changed to accomodate the changes in the

- premain valve body. See Figure 6 for the previous design spacer plate and Figure 7 for the new design.
  - The premain valve body upper side casting was changed and a screen was added in line pressure
- feed passage to the solenoid reducing valve. Refer to Figure 8 for previous design casting and Figure 9 for the casting change and the added screen.
  - The premain valve body lower side and the lock-up control valve were changed. Refer to Figure
- 10 for the previous design lock-up control valve installation. Refer to Figure 11 for the new design lock-up control valve and its installation. NOTE: the valve is bored on the opposite side, to accommodate the new spring placement on the opposite side.
  - The premain cover, spacer plate and gaskets were changed and the tube on the exterior was
- eliminated. Refer to Figure 12 to see the previous design. Refer to Figure 13 to see the new design.
- Refer to Figure 14 for an Oil Circuit diagram outlining the pressure control hydraulic circuit and the TCC Control Valve as well as the function of the exterior tube.
- Refer to Figure 15 for an Oil Circuit diagram outlining the pressure control hydraulic circuit,
- the added Solenoid Reducing valve and its function and the added line pressure passage to the TCC Control Valve.

#### **INTERCHANGEABILITY:**

None of the parts listed above can be used in any previous models. However, when using the complete 1998 valve body as a service package, it will retro-fit back to previous models, equipped with the F4E-III transaxle.

Copyright © 2001 ATSG

02-22 Page 1 of 16



#### F4E-III VALVE AND PASSAGE I.D.




Figure 1
AUTOMATIC TRANSMISSION SERVICE GROUP

02-22 Page 2 of 16



#### F4E-III VALVE AND PASSAGE I.D.




Figure 2
AUTOMATIC TRANSMISSION SERVICE GROUP

02-22 Page 3 of 16



#### F4E-III VALVE AND PASSAGE I.D.




Figure 3
AUTOMATIC TRANSMISSION SERVICE GROUP

02-22 Page 4 of 16



#### F4E-III VALVE AND PASSAGE I.D.




Figure 4
AUTOMATIC TRANSMISSION SERVICE GROUP

02-22 Page 5 of 16



#### F4E-III VALVE AND PASSAGE I.D.




Figure 5
AUTOMATIC TRANSMISSION SERVICE GROUP



#### F4E-III VALVE AND PASSAGE I.D.




Figure 6

02-22 Page 7 of 16



#### F4E-III VALVE AND PASSAGE I.D.




Figure 7

02-22 Page 8 of 16



#### F4E-III VALVE AND PASSAGE I.D.




Figure 8

02-22 Page 9 of 16



#### F4E-III VALVE AND PASSAGE I.D.




Figure 9

02-22 Page 10 of 16



### F4E-III VALVE AND PASSAGE I.D.




Figure 10

02-22 Page 11 of 16



#### F4E-III VALVE AND PASSAGE I.D.




Figure 11

02-22 Page 12 of 16



#### F4E-III VALVE AND PASSAGE I.D.




Figure 12
AUTOMATIC TRANSMISSION SERVICE GROUP

02-22 Page 13 of 16



#### F4E-III VALVE AND PASSAGE I.D.




Figure 13

02-22 Page 14 of 16






Figure 14
AUTOMATIC TRANSMISSION SERVICE GROUP

02-22 Page 15 of 16






Figure 15
AUTOMATIC TRANSMISSION SERVICE GROUP

02-22 Page 16 of 16