

## **Technical Service Information**

## CHRYSLER A500/518 PREMATURE OVERDRIVE CARRIER FAILURE

**COMPLAINT:** Premature failure of overdrive carrier and bearing. The bearing is actually destroyed first

and the bearing takes out the overdrive carrier.

**CAUSE:** The cause is lack of lube oil to the carrier bearing.

**CORRECTION:** Replace the bearing and overdrive carrier. BEFORE installing the new overdrive carrier,

machine a chamfer on the inside diameter that is .050" wide as shown in Figure 1. This will

provide more lube oil for the carrier bearing.




Figure 1

Copyright © 2000 ATSG