











-3A1
/4.0

32 INPUTS

MITSUBISHI

IP : 192.168.3.250

FX5U-64M


32 OUTPUTS

-3A2

MITSUBISHI

IP : 192.168.3.18

GS2107-WTBD-N



Rollers and Pin Wheel Off	Motor protection fault	Pin wheel In clockwise rotation	Pin wheel In anti-clockwise rotation	Rollers On	Parts Counter	Magazine sleeve bunker full	pole sleeves not ejected
---------------------------	------------------------	---------------------------------	--------------------------------------	------------	---------------	-----------------------------	--------------------------





