INSPECTION REPORT

Report No. DRF-INS-0001 Project: Driftwood Date: 2024-02-21
Inspector: P. Ivanova

Item results

BV-8492 Ball valve hydrostatic test at 300 psi - PASS
HX-1475 Plate heat exchanger hydrostatic test at 1500 psi - PASS

All items visually examined for leaks, weld defects and marking legibility.