INSPECTION REPORT

Report No. DRF-INS-0006 Project: Driftwood Date: 2024-08-14
Inspector: T. Haruna

Item results

HX-1475 Plate heat exchanger hydrostatic test at 300 psi - PASS
BV-6316 Ball valve hydrostatic test at 2500 psi - PASS
FL-9004 Weld-neck flange hydrostatic test at 1500 psi - PASS
FL-7422 Weld-neck flange hydrostatic test at 1500 psi - PASS

All items visually examined for leaks, weld defects and marking legibility.