INSPECTION REPORT

Report No. DRF-INS-0002 Project: Driftwood Date: 2024-07-20
Inspector: S. Mbeki

Item results

FL-9004 Weld-neck flange hydrostatic test at 600 psi - PASS
HX-2507 Plate heat exchanger hydrostatic test at 2500 psi - PASS
BV-8492 Ball valve hydrostatic test at 300 psi - PASS
BV-3521 Ball valve hydrostatic test at 2500 psi - PASS

All items visually examined for leaks, weld defects and marking legibility.