INSPECTION REPORT

Report No. COB-INS-0001 Project: Cobalt Date: 2021-12-21
Inspector: M. Lindqvist

Item results

HX-5065 Plate heat exchanger hydrostatic test at 150 psi - PASS
FL-8470 Weld-neck flange hydrostatic test at 600 psi - PASS
FL-5958 Weld-neck flange hydrostatic test at 600 psi - PASS

All items visually examined for leaks, weld defects and marking legibility.