INSPECTION REPORT

Report No. DRF-INS-0003 Project: Driftwood Date: 2021-06-11
Inspector: A. Delacroix

Item results

HX-1475 Plate heat exchanger hydrostatic test at 300 psi - PASS

BV-8492 Ball valve hydrostatic test at 300 psi - PASS

FL-7422 Weld-neck flange hydrostatic test at 1500 psi - PASS

All items visually examined for leaks, weld defects and marking legibility.