## LEGv8 operands

Name	Example	Comments	
32 registers	X0-X30, XZR	Fast locations for data. In LEGv8, data must be in registers to perform arithmetic, register XZR always equals 0.	
2 <sup>62</sup> memory words	Memory[0], Memory[4], , Memory[4,611,686,018,427,387, 904]	Accessed only by data transfer instructions, LEGv8 uses byte addresses, so sequential doubleword addresses differ by 8. Memory holds data structures, arrays, and spilled registers.	

## LEGv8 assembly language

Category I	structionExample		Meaning	Comments
	add	ADD X1, X2, X3	X1 = X2 + X3	Three register operands
Arithmetic	subtract	SUB X1, X2, X3	X1 = X2 X3	Three register operands
	add immediate	ADDI X1, X2, 20	X1 = X2 + 20	Used to add constants
	subtract immediate	SUBI X1, X2, 20	X1 = X2 — 20	Used to subtract constants
	add and set flags	ADDS X1, X2, X3	X1 = X2 + X3	Add, set condition codes
	subtract and set flags	SUBS X1, X2, X3	X1 = X2 — X3	Subtract, set condition codes
	add immediate and set flags	ADDIS X1, X2, 20	X1 = X2 + 20	Add constant, set condition codes
	subtract immediate and set flags	SUBIS X1, X2, 20	X1 = X2 — 20	Subtract constant, set condition codes
	load register	LDUR X1, [X2,40]	X1 = Memory[X2 + 40]	Doubleword from memory to register
	store register	STUR X1, [X2,40]	Memory{X2 + 40} = X1	Doubleword from register to memory
	load signed word	LDURSW X1,[X2,40]	X1 = Memory[X2 + 40]	Word from memory to register
	store word	STURW X1, [X2,40]	Memory[X2 + 40] = X1	Word from register to memory
	load half	LDURH X1, [X2,40]	X1 = Memory[X2 + 40]	Halfword memory to register
	store half	STURH X1, [X2,40]	Memory[X2 + 40] = X1	Halfword register to memory
	load byte	LDURB X1, [X2,40]	X1 = Memory[X2 + 40]	Byte from memory to register
	store byte	STURB X1, [X2,40]	Memory[X2 + 40] = X1	Byte from register to memory
Data transfer	load exclusive register	LDXR X1, [X2,0]	X1 = Memory[X2]	Load; 1st half of atomic swap
	store exclusive register	STXR X1, X3 [X2]	Memory[X2]=X1;X3=0 or 1	Store; 2nd half of atomic swap
	move wide with zero	MOVZ X1,20, LSL 0	X1 = 20 or 20 * 2 <sup>16</sup> or 20 * 2 <sup>12</sup> or 20 * 2 <sup>46</sup>	Loads 16-bit constant, rest zeros
	move wide with keep	MOVK X1,20, LSL 0	X1 = 20 or 20 * 2 <sup>16</sup> or 20 * 2 <sup>32</sup> or 20 * 2 <sup>46</sup>	Loads 16-bit constant, rest unchanged
Logical	and	AND X1, X2, X3	X1 = X2 & X3	Three reg. operands; bit-by-bit AND
	inclusive or	ORR X1, X2, X3	X1 = X2   X3	Three reg. operands; bit-by-bit OR
	exclusive or	EOR X1, X2, X3	X1 = X2 ^ X3	Three reg. operands; bit-by-bit XOR
	and immediate	ANDI X1, X2, 20	X1 = X2 & 20	Bit-by-bit AND reg, with constant
	inclusive or immediate	ORRI X1, X2, 20	X1 = X2   20	Bit-by-bit OR reg. with constant
	exclusive or immediate	EORI X1, X2, 20	X1 = X2 ^ 20	Bit-by-bit XOR reg. with constant
	logical shift left	LSL X1, X2, 10	X1 = X2 << 10	Shift left by constant
	logical shift right	LSR X1, X2, 10	X1 = X2 >> 10	Shift right by constant
Conditional branch	compare and branch on equal 0	CBZ X1, 25	if (X1 == 0) go to PC + 100	Equal 0 test; PC-relative branch
	compare and branch on not equal 0	CBNZ X1, 25	if (X1 != 0) go to PC + 100	Not equal 0 test; PC-relative branch
	branch conditionally	B.cond 25	if (condition true) go to PC + 100	Test condition codes; if true, branch
Unconditional branch	branch	B 2500	go to PC + 10000	Branch to target address; PC-relative
	branch to register	BR X30	go to X30	For switch, procedure return
	branch with link	BL 2500	X30 = PC + 4; PC + 10000	For procedure call PC-relative