

TEAM PALO



PALO MODELT



HARDWARE

- Sonar position issues
- •Steering issues
- Quick building prototype



SOFTWARE

- •PID powered algorithm
- Sonar exceptions

COSTS

- •To develop the Palo Model T we've spent a total of 1800 LeoCoins
- •To test the Palo model T on the circuit we've spent 475 more LeoCoins

