

A4.1 Fraser River South Arm North Bank



Photo 1: Degraded riparian and intertidal habitat along the northern shoreline of Canfisco Bay.



Photo 2: Sparse vegetation patches in historic compensation bench, within the Canfisco site.



Photo 3: Pocket marsh along the Fraser River protected by riprap berm.



Photo 4: Riparian vegetation along the north arm of the Fraser River.

A4.2 Deas Island



Photo 5: Riprap slopes along the north shore of Deas Island.



Photo 6: Pocket marsh within the riprap slope along the north shore of Deas Island.



Photo 7: Riparian trees partially overhanging riprap along the north shore of Deas Island.



Photo 8: Mudflat and estuarine shore marsh west of Deas Island Bridge.



Photo 9: Estuarine channel west of Deas Island Bridge.



Photo 10: Estuarine shore marsh vegetation along the south shore of Deas Island, east of Deas Island Bridge.



Photo 11: Estuarine channel vegetation along the south shore of Deas Island, east of Deas Island Bridge.



Photo 12: Tidal freshwater swamp vegetation along the south shore of Deas Island, east of Deas Island Bridge.

A4.3 Deas Slough



Photo 13: Mudflats and riprap berms along the south shoreline of Deas Slough, east of Deas Island Bridge.



Photo 14: Green Slough looking upstream near the Millenium Trail pedestrian crossing.



Photo 15: Estuarine vegetation along the left bank of Green Slough.



Photo 16: Riparian and estuarine vegetation along the right bank of Green Slough.

A4.4 Upland Watercourses



Photo 17: Watercourse 7, looking upstream from flow control structure near the confluence with the Fraser River.



Photo 18: Watercourse 7, looking upstream from Rice Mill Road.



Photo 19: Watercourse 28, looking northward from Rice Mill Road.



Photo 20: Watercourse 29, looking upstream from CN rail crossing.



Photo 21: Watercourse 29, looking downstream from CN rail crossing.



Photo 22: Watercourse 10, looking upstream along right bank.



Photo 23: Watercourse 10, downstream along right bank.



Photo 24: Watercourse 11, looking westward along Rice Mill Road.



Photo 25: Watercourse 15, looking westwards along River Road.



Photo 26: Watercourse 15, looking eastward along River Road.



Photo 27: Watercourse 16, looking upstream from confluence with Watercourse 15.



Photo 28: Watercourse 18, looking downstream from Highway 99.



Photo 29: Watercourse 18, looking downstream along River Road.

A4.5 Offsetting Locations



Photo 30: Historic compensation bench east of the Deas Slough shoreline offset location.



Photo 31: Historic compensation bench west of the Deas Slough shoreline offset location.



Photo 32: Estuarine shore marsh within the Deas Slough shoreline offset site.



Photo 33: Erosional scarp dividing upper and lower intertidal habitats within the Deas Slough Shoreline offset site.



Photo 34: Created marsh habitat at the confluence of Green Slough and Deas Slough.