



3.8 Barge

One Barge needs to be built. Tools & Equipment (for 1x Barge)


- 7/16" wrenches/sockets
- ¾" wrenches /sockets
- 15/16" wrenches/sockets
- 50 lb. cable ties, white
- 50 lb. cable ties, black (ONLY USE ON REEFSCAPE LOGO PLASTIC)
- 120 lb. cable ties
- 6x ½-13 eye nuts
- 6x ½-13 shoulder eye bolts
- 8x 1/4-20 x 1" hex head bolts
- 10x 1/2-13 x 1.25" hex bolts
- 10x ½-13" nylock nuts
- 12x ½" flat washers
- Tackle box of truss hardware
- 24x ¼" x 2-5/16" pins





3.8.4 Assembly





2.






3.

Attach shoulder eye bolts to the cages using hardware shown.
Tighten so that the cages do not spin freely, but can still rotate by hand with some difficulty.

Units Needed: 3 Red, 3 Blue








Align with P10

Position bases as shown

Align with P11

Position so there is a 1" gap between base and guardrail base and guar








7. IMPORTANT: Incorrect truss orientation will cause significant delays in your build time.

Make sure truss diagonals are forming "W" and not "M"


4-way connector should have mounting plates facing up


Thes mounting faces should be vertical, as shown.


















Rib should rest directly on tube here.

Insert 6 ribs at those locations. The ribs should be placed on the side of the tube that faces the center of the field. Secure with 120lb. cable ties

Solid Modeling Solutions Partner











firstinspires.org/robotics/frc












Gest Nam



























20.



Modeling Solutions Partner





Attach Top Diffuser plastic using white, 50lb. cable ties. Only use the inside slots at this time.


Attach Side Diffuser, Top
Diffuser, Small, and vinyl plastic
using 50lb. cable ties. Use black
cable ties to attach the vinyl
plastic.





23.

Hang the cages using two carabiners and chain.
Please note, cages should be in the low position
to start each day.





3.8.5 Electronics

3.8.5.1 Equipment

- 6 5' extensions
- 6 Alliance Colored Lights wrapped around an acrylic tube. (3 Red and 3 Blue)

3.8.5.2 Barge Wiring

 The Alliance colored lighting is installed in the Barge during the construction phase (Step 13). If the extension cords were not installed with the lights, it should be done now. An example of cable tying the lights in is shown below.















 All cords should be cable tied to ensure they do not hang below the truss and no robot gets snagged on one. Example shown below.



Run the cables down the inside of truss leg to the base. See Section 3.7.3 for more
details about how this lighting cables connect to their associated relay box.

