

- Filename: intro-to-iot-pentesting-6-1-1-manually-identifying-uart-pins.md
- Show Name: Intro to IoT Pentesting
- Topic Name: Hardware Hacking
- Episode Name: Manually Identifying UART Pins

=====

Manually Identifying UART Pins

Objectives:

- Use a multimeter and knowledge of UART pin functions to determine UART pinout on an unlabeled PCB

-
- Find GND pin
 - Continuity Test
 - Determine RX, TX, and VCC pins
 - RX
 - Typically lower voltage than other pins
 - Also not much variance in voltage
 - TX
 - Typically has a lot of variance in voltage
 - Can see voltages that are close to VCC
 - Check each pin during boot to catch voltage changes due to data output
 - VCC
 - Typically close to full voltage (3.3)
 - Not much variance in voltage if any