



SKILL FORGE
WHERE STUDENTS BECOME TEACH

SOP-600 — Complete TPU Installation Workflow

Section 7: Colored TPU

SOP · Version 1.0

Organization: _____

Document ID: sop-600-complete-tpu-installation-
workflow

Effective Date: _____

Approved By: _____

SOP-600 — Complete TPU Installation Workflow

Forge Standard Operating Procedures v1.0

Section 7: Colored TPU

Purpose

End-to-end procedure for colored TPU (paint protection with color) installation.

Scope

Colored TPU color-change and protection packages. Combines PPF technique with wrap-level coverage planning.

Procedure

Pre-install

1. Complete SOP-200 through SOP-204.
2. Verify color batch match across all rolls — same lot number.
3. Plan seam placement away from primary sight lines.

Surface prep

1. Same standard as SOP-400 — wash, decon, IPA per panel.
2. Higher paint correction standard — TPU shows defects more than clear PPF.

Application

1. Handle TPU with gloves — oils affect color coat.
2. Slip solution ratio per TPU manufacturer — often less slip than clear PPF.
3. Squeegee with felt edge; avoid repeated passes on color face.
4. Post-heat to spec — overheating yellows or hazes color TPU.

Seams & edges

1. Overlap seams in hidden areas; use manufacturer-approved seam tape if required.
2. Edge seal with primer only where manual specifies.

QC

1. Color consistency check under multiple light sources.
2. Complete SOP-205 and SOP-206.

Quality standards

☐ Batch lot recorded on work order

☐ No color haze or orange peel from over-heating

Related documents

Document	ID
PPF Master Install Manual	ppf-master-install
Vinyl Wrap Master Install Manual	vinyl-wrap-master-install
Complete PPF Installation Workflow	sop-400-complete-ppf-installation-workflow

Revision history

Version	Date	Author	Changes
1.0	2026-07-23	Forge Operations	Initial release

Confidential — Skill Forge training operations.