Console

1s Compliment of 00010011=
1. 1. 1. 0. 1. 1. 0. 0.
2s Compliment of 00010011=
1. 1. 1. 0. 1. 1. 0. 1.

1s Compliment of 01110110=
 1. 0. 0. 0. 1. 0. 0. 1.
2s Compliment of 01110110=
 1. 0. 0. 0. 1. 0. 1. 0.

1s Compliment of 11101101=
0. 0. 0. 1. 0. 0. 1. 0.
2s Compliment of 11101101=
0. 0. 0. 1. 0. 0. 1. 1.

1s Compliment of 10000001= 0. 1. 1. 1. 1. 1. 0. 2s Compliment of 10000001= 0. 1. 1. 1. 1. 1. 1. 1.

1s Compliment of 10000000= 0. 1. 1. 1. 1. 1. 1. 1. 2s Compliment of 10000000= 1. 0. 0. 0. 0. 0. 0. 0.