## Console

1s Compliment of 00010011= 1. 1. 1. 0. 1. 1. 0. 0.

1s Compliment of 01110110= 1. 0. 0. 0. 1. 0. 0. 1.

1s Compliment of 11101101= 0. 0. 0. 1. 0. 0. 1. 0.

1s Compliment of 10000001= 0. 1. 1. 1. 1. 1. 0.

1s Compliment of 10000000= 0. 1. 1. 1. 1. 1. 1. 1.

1s Compliment of 00000000= 1. 1. 1. 1. 1. 1. 1. 1.