Rf = 7962 ohm

R1 = 796.2 ohm

Cf = $0.01 \mu farad$