Driver Controller

Intake

"Shoot"

Reset NAVX

Reset NAVX
to 180

Drive Strafe

X Mode

Drive Spin
(side-to-side)

2023.03.02