

Machine: Raptor X-SL CNC

Assignment:

- -Create the part in CAD
- -Use CAM to program toolpaths for machine
- -Mill out shape out of stock
- -Match dimensions with reasonable accuracy
- -Remove any tabs and deburr edges



PARTS LIST										
ITEM	(QTY		PART NUMBER			DESCRIPTION			
1		1	MP1	-001			Mounting plate			
2		4	M6 x	x 16			ISO metric hex socket screw			rew
Drawn by Date Benjamin Solar				2024-02-20 W			All units in metric General Tolerance: ISO 2768-1M			
FABLAB WORKSHOP				Mount Plate ASM				Sharp corners broken ISO unless otherwise spec.		
				Part	MP1	Stock	-	Scale 1:1	Rev: 2	Sheet 1 / 1

4

