

Machine: Raptor X-SL CNC

Assignment:

- -Create the part in CAD
- -Use CAM to program toolpaths for machine
- -Mill out shape out of stock
- -Match dimensions with reasonable accuracy
- -Remove any tabs and deburr edges



Extra Challenge: Use fixture to hold part

PARTS LIST											
ITEM	(QTY		PART NUMBER			DESCRIPTION				
1		1	MP1	-001	Moun		Mounting	ng plate			
2		4	M6 x	x 16			ISO metric hex socket screw				
Drawn by Benjamin Solar				2024-02-20 WEI			All units in metric General Tolerance: ISO 2768-1M				
	ABLAB		Mount Plate ASM				Sharp corners broken ISO unless otherwise spec.				
WORKSHOP				Part	MP1	Stock	_	Scale 1:1	Rev: 2	Sheet 1 / 1	

4

