

Machine: Raptor X-SL CNC


Assignment:

- -Create the part in CAD
- -Use CAM to program toolpaths for machine
- -Mill out shape out of stock
- -Match dimensions with reasonable accuracy
- -Remove any tabs and deburr edges



PARTS LIST											
ITEM	QTY		PART I	NUMB	ER	DESCRIPTION					
1	1	MP1	-001			Mounting plate					
2	4	M6 :	x 16			Hex socket screw					
Drawn by Benjamin S	24-11-16	1-16 WEDU			All units in metric General Tolerance: ISO 2768-1M						
	Mounting plate			Sharp corners broken ISO unless otherwise spec.							
WORKSHOP			Part	MP1	Stock	_	Scale 1:1	Rev: 3	Sheet 1 / 1		

4





Job name:	WEDU	Program No. :	MP1-001_CAM1	Machining time
Date created:	5-011-2024	Comment:	OP1	7m:12s

SETUP		
sтоск	PART	
X: 160.00	X: 100.00	
Y: 160.00	Y: 100.00	
Z: 15.00	Z: 15.00	
	G54	
SETUP NOTES		
All units are metric.		

TOOLS										
Type	Т	Ξ	DIA	NoF	Desc.	CMT	BL	Shaft	Vendor	ID
flat end mill	T1	H1	ø10	2	2F Dual Ply cutter	Plywood	47.8	ø10	Onsrud	60-155MC
flat end mill	T2	H2	ø5	1	1F Upward Spiral	N1.1 Hard Plastic	25	Ø6	LMT Belin	13050B