

Machine: Raptor X-SL CNC

Assignment:

- -Create the part in CAD
- -Use CAM to program toolpaths for machine
- -Mill out shape out of stock
- -Match dimensions with reasonable accuracy
- -Remove any tabs and deburr edges



Extra Challenge: Use fixture to hold part

PARTS LIST									
ITEM	QTY	Y PART I			ER	DESCRIPTION			
1	1	MP1	-1001			Mounting plate			
2	4	M6 x	x 16			ISO metric hex socket screw			
Drawn by Date Benjamin Solar 20:			24-02-20	W	orkshop	EDU	All units in metric General Tolerance: ISO 2768-1M		
FABLAB			Mount Plate ASM				Sharp corners broken ISO unless otherwise spec.		
W	ORKSHOP	,	Part	MP1	Stock	_	Scale 1:1	Rev: 1	Sheet 1 / 1

4

