
20 tracked supermodes: LP modes of the cladding guide (left) become the 19 core modes (right)
effective index of the supermodes
1.450
1.448
1.446
1.444
1.442
1.440
1.438
cladding index
jacket index
0
20
40
60
80
100
z along the taper (mm)