
pl7_1200 transfer matrix at 1200 nm (columns: launch one mode, read the ports)
|A|^2: power from input mode n to port k
output port k
input (multimode) mode n
arg A: fixed relative phases
input (multimode) mode n