## Specman Tutorial, Product Version 8.1

## **Installing the Specman 8.1 Tutorial**

Use the procedure below to install the Specman 8.1 Tutorial. After you complete this procedure, you will be ready to start using the tutorial by following the instructions in the Specman Tutorial PDF file.

- 1. Download the tutorial tar file: sn 8.1 tutorial.tar.gz
- 2. Move the sn 8.1 tutorial tar gz file to the directory where you will install the tutorial.

For example, suppose you will install the tutorial in a directory named /cad/vrst/8.1.

```
mv sn_8.1_tutorial.tar.gz /cad/vrst/8.1
```

3. Change to the directory where you will install the tutorial.

```
cd /cad/vrst/8.1
```

4. Unzip and untar the sn\_8.1\_tutorial.tar.gz file.

```
gzip -d sn_8.1_tutorial.tar.gz
tar xvf sn_8.1_tutorial.tar .
```

This installs the following tutorial files in /cad/vrst/8.1:

```
sn_8.1_tutorial.pdf -- The Tutorial in PDF format
sn 8.1 tutorial -- The directory that holds the tutorial files
```

5. Open sn\_8.1\_tutorial.pdf and follow the instructions to run the tutorial.

Note that Appendix A lists the files that appear in the sn\_8.1\_tutorial directory.

1 of 1 10/16/2009 09:48 AM