B=1.25a B=1.25a 2+1.35a=360° a=360=180° B=1.25a=200° S=1180-a1=20° Rocker=04B=5 Crank=02A=1.65 Ground=0402=4.8

