



FAMAX QC SYSTEM

IPQC, IQC & OQC

Faiz Fazli


faiz.fazli@fmefamax.com

Table of Contents


GENERAL USER GUIDE	2
USER GUIDE BY ROLE ACCESS	7
ENGINEER ACCESS	8
REGISTER ACCESS	11
PRODUCTION ACCESS.....	19

GENERAL USER GUIDE

1. Enter Famax QC System by clicking this link
<http://192.168.0.5/FamaxQCSysstem/index.html>
2. Main page will show as below image.



3. The user can/only click the button in red box.



4. When user performing
 - i. Buy-Off – Then click “Buy-Off Checking” button.
 - ii. IPQC – Then click “IPQC Checking” button.
 - iii. IQC – Then click “IQC Checking” button.
 - iv. OQC – Then click “OQC Checking” button.

5. The image shows what happens once “IPQC Checking” button is clicked.
- First you must select Part Name from the dropdown box.

The screenshot shows the IPQC System interface. At the top left is the 'IPQC System' logo, and at the top right is a button labeled 'Active Job Orders'. The main content area features a 'Process Selection' dialog box with the instruction 'Please select the details below to begin inspection'. Inside the dialog, the 'Part Name' section has a dropdown menu that is open, displaying a search bar and a list of parts: 'MC 704 STEM' (highlighted), '5 KNOCKOUT DIE', 'SCREW DRIVE EVT12PC - T0207620', 'SCREW DRIVE EVT12PC - T0207620', and 'VIS DE COMMANDE (HVT50P)'. The background is a light blue gradient.

© 2025 Famax Technology (M) System. All rights reserved.

- Then all IPQC process related to the part chosen will be shown. Select the process.

The screenshot shows the IPQC System interface. At the top left is the 'IPQC System' logo, and at the top right is a button labeled 'Active Job Orders'. The main content area features a 'Process Selection' dialog box with the instruction 'Please select the details below to begin inspection'. Inside the dialog, the 'Part Name' section now shows 'MC 704 STEM' in the dropdown. The 'Manufacturing Process' section has a dropdown menu that is open, displaying a search bar and a list of processes: 'CUTTING' (highlighted), 'MILLING 1', 'MILLING 2', 'STAMPING 1', and 'STAMPING 2'. The background is a light blue gradient.

© 2025 Famax Technology (M) System. All rights reserved.

6. Then, system will ask for JO Number and select machine number from the dropdown and click “Continue” button.

IPQC System Active Job Orders

Process Selection

Please select the details below to begin inspection

Part Name
MC704 STEM (MC416204)

Manufacturing Process
CUTTING

Job Order Number
JQ/171125/01328

Machine Number
AC01

Continue

© 2025 Famax Technology (M) Sdn. Bhd. All rights reserved.

7. This will be the screen after clicking “Continue”.
 - a. Fill in the checker’s name in the first red box
 - b. Fill in the reading for each zone.
 - c. After that click next to process.

Note : Wrong values would prompt telegram alert, so make sure take correct reading.

IPQC Checking System

PART NAME: MC704 STEM (MC416204) | PROCESS: CUTTING | JOB ORDER: JQ/171125/01328 | MACHINE: AC01

INSPECTOR NAME: Enter name...

Measurement Progress: 1 / 2

Zone 1

Instrument	QC Class
DC	QC
Min / OK	Max / NG
32.44	32.5

READING 1: 0.00
READING 2: 0.00
READING 3: 0.00

BACK NEXT

1 | Cutting

Noted :
1) cutting length 77.50mm +/-0.50
2) auto cut slanting not more than 77.00 from flat side.
3) all dimension measure by digital caliper .
4) minimize the dented and scratched upon to machining shop .

(1) DC 32.50 (h9) 32.44

(2) DC 77.50 +/-0.5

d. Complete all reading zones and click submit all reading buttons.

IPQC Checking System

PART NAME	PROCESS	JOB ORDER	MACHINE	INSPECTOR NAME
MC704 STEM (MC416204)	CUTTING	JO/171125/01328	AC01	Training

1 Cutting

Noted :

- 1) cutting length 77.50mm +/-0.50
- 2) auto cut slanting not more than 77.00 from flat side.
- 3) all dimension measure by digital caliper .
- 4) minimize the dented and scratched upon to machining shop .

(1) DC

32.50
32.44

(2) DC

77.50 +/-0.5

Measurement Progress

✓ 2

Zone 2

2

Instrument	QC Class
DC	QC
Min / OK	Max / NG
77	78

READING 1

77

READING 2

77


READING 3

77

BACK

SUBMIT REPORT

8. Message will prompt out if there is out of spec measurements and this will notify management.



9. You will then be redirected to summary page where you can see the wrong readings. The red column shows wrong reading, so take necessary action like informing technician or engineer.

- a. Click on “Finish Report” button

IPQC Checking System

Inspection Summary

PART NAME MC704 STEM (MC416204)	PROCESS CUTTING	JOB ORDER JO/171125/01328	MACHINE AC01	INSPECTOR NAME Training
---------------------------------------	--------------------	------------------------------	-----------------	----------------------------

Zone 1: 1

MEASUREMENT	READING 1	READING 2	READING 3
Range: 32.44 - 32.5	32.44	32.44	32.44

Zone 2: 2

MEASUREMENT	READING 1	READING 2	READING 3
Range: 77 - 78	77	77	77

Inspector Remarks

Enter any additional observations, issues, or comments here...


FINISH REPORT

10. It will return to the main page.

11. All process is the same for IPQC, IQC and OQC but for IQC and OQC have and button “Inspection Guide”. If click that button, then you can straight view inspection guide if you have anything to refer.

USER GUIDE BY ROLE ACCESS

1. There is a login button. Click the button. This is accessible with credential only.



2. Click “Login” and it will be prompt this box.

Admin Login

User ID

Enter your user ID


Password

Enter your password

Cancel


Login

a. Below shows images of access level.



All access has no buttons blocked. Only administrators are allowed to access all functions.

ENGINEER ACCESS



ENGINEER access can only access Generate New File, Remove Folder.

3. Now, when you click “Generate New File” button. You will get a page as below.

← Back to Dashboard

Generate New File

Part Information

PART DESCRIPTION e.g. Housing Bracket	PART NO e.g. A-12345
W.L. NUMBER e.g. WIN-*	DRAWING NUMBER e.g. DRW-*
REVISION NUMBER e.g. 01	RAW MATERIAL e.g. Aluminum
MATERIAL GRADE e.g. 6061-T6	
MATERIAL SIZE e.g. Ø50mm x 100mm	

Process Flow

#	Process Name	Process Image (Optional)	Document	FlowChart	Action
1	Name		IQC	FABRICATION	Remove

+ Add Process Step

Submit & Generate

© 2025 Famax Technology (M) Sdn. Bhd. All rights reserved.

4. Make sure all cells are filled and all process is determined before generating document for the process.
DO NOT USE process name as: Milling (M1). Avoid bracket.
Then click submit button.

← Back to Dashboard

Generate New File

Part Information

PART DESCRIPTION Part Name	PART NO PartNo123
W.L. NUMBER Win-1234	DRAWING NUMBER DRW-4321
REVISION NUMBER 00	RAW MATERIAL RawMaterial A
MATERIAL GRADE A123	
MATERIAL SIZE Ø250*10*	

Process Flow

#	Process Name	Process Image (Optional)	Document	FlowChart	Action
1	Testing Process		IQC	FABRICATION	Remove

+ Add Process Step

Submit & Generate

1. Page will be auto redirected if there is no error occur. Fill in everything properly and click submit. Once click submit wait patiently as it may take some time. Wait until the pdf saved message pops out successfully. If anything, error please inform IT department immediately. Do Not RETRY

← Back



FAMAX TECHNOLOGY (M) SDN BHD
200601028954 (748710-K)
PROCESS FLOW DIAGRAM

PART NO: PartNo123
PART NAME: Part Name (PartNo123)

ENGINEER: Faiz Test
DEPT: IT
REVISION: 00

DATE: 22/12/2025


STEP	FLOW	OPERATION DESCRIPTION	PRODUCT CHARACTERISTIC (KPC)	CONTROL CHARACTERISTIC (KCC)
1		Testing Process	Enter KPC	Enter KCC

[Submit & Save](#)


2. The page will be redirected to Admin Home Dashboard.

REGISTER ACCESS


1. Now, let's move to "Add Part" Button. This part is done by Register only after all documents are done properly.




2. Choose the part name. We will do for "Part 1A" now.
 - a. Select Part Name from dropdown field.
 - b. Choose folder that contains all Excel files.



3. Upload the completed folder that contains all excel files.




4. Do not disturb the setting as all will be detected automatically. And then click “Submit Folder” button.



5. After uploading the folder consist of excel, the system will redirect to this page. Please upload the image folder consist of the product process image.

The screenshot shows a web interface titled 'Part Image Upload'. At the top, there is a blue header bar with a checkmark icon and the title. Below the header, there are two fields: 'TARGET PART' with the value 'Part Name (PartNo123)' and 'EXPECTED PROCESSES' with the value '1'. In the center, there is a large dashed box containing a folder icon and the text 'Click to Select Image Folder'. Below this box are two buttons: 'Start Upload' and 'Reset Form'. At the bottom left, there is a link 'Show Technical Logo'. The footer contains the copyright notice '© 2025 Famax Technology (M) Sdn. Bhd. Technology (M) Systems. All rights reserved.'

6. Here you must add folder containing all images. Image name and Process name must match. IQC and OQC must add pdf of Inspection guide as well. Then, click “Start Upload” button. Make sure no errors, if ERROR report immediately.



← Back to Excel Upload

Part Image Upload

TARGET PART
Part Name (PartNo123)

EXPECTED PROCESSES
1

Click to Select Image Folder

TURNING_IPQC.png

Testing Process

IPQC

Remove


Start Upload

Reset Form

[Show Technical Logs](#)

© 2025 Famax Technology (M) Sdn. Bhd. Technology (M) System. All rights reserved.

7. If folder successfully uploaded, user will be redirected to Admin Home Dashboard.
8. Next, is for “Revision” button.



9. Once this button is clicked, select the Document Type > Part Name > Process. Process related only will be shown as dropdown option.

← Back to Dashboard

Document Revision

Document Type
x IPQC

Part Name
x Part Name (PartNo123)

Process
x TestingProcess

Upload Revision File (.xlsx)

Choose File
V2_TestingProcess_IPQC.xlsx

Expected format: Vx_TestingProcess_IPQC.xlsx

Continue to Image Revision

© 2025 Famax Technology (M) Sdn. Bhd. All rights reserved.

10. Once you have chosen the process you must upload the latest excel file. The file naming must be controlled. So the latest file must be **Vx_Milling 1_IPQC.xlsx**. Let's say document is use is V2 the latest one must be V3.

Process

x TestingProcess ▼

Upload Revision File (.xlsx)

Choose File

V3_TestingProcess_IPQC.xlsx

Expected format: Vx_TestingProcess_IPQC.xlsx

Continue to Image Revision

Example Filing Name

11. Then, click “Continue to Image Revision” button. You will redirect to the next page to upload the image. Only one image can be uploaded. If “IQC” document or “OQC” document the must upload pdf as well. Then, click “Complete Revision” button.

Upload Revision Files

TYPE

IPQC

PART NAME

Part Name (PartNo123)

PROCESS

TestingProcess

PROCESS ID

TestingProcess

REFERENCE FILE

V3_TestingProcess_IPQC.xlsx

Process Image *

Drag image here or click to browse

V3_TestingProcess_IPQC.xlsx.png


View Remove

Complete Revision

Reset Form

[Show Technical Logs](#)

12. After the process is complete, it will redirect to the Admin Home Dashboard.
13. Finally, for Register Access, user can generate report.



14. Generate report consists of 2 types of generated report.

- a. By Parts.
- b. All Parts.


15. By Parts, users can generate reports by choosing Daily, Weekly or Monthly Reports.

The image displays two side-by-side screenshots of a web application's 'Report Generator' interface. Both screenshots have a 'Back to Dashboard' link at the top left. The left screenshot shows the 'Part Check Sheet (Detailed)' option selected with a red radio button, and the 'Monthly' option selected for the 'Select Period' dropdown. A red box highlights the 'Part Check Sheet (Detailed)' and 'Monthly' options, and another red box highlights the 'Show Active Parts (By Date)' link. The right screenshot shows the 'Monthly Summary (All Parts)' option selected with a red radio button, and the 'Monthly' option selected for the 'Select Period' dropdown. A red box highlights the 'Monthly Summary (All Parts)' and 'Monthly' options. Both screenshots show a 'Download Report' button and a status message 'Found 8 Records. Generating Excel...'.

16. Users can see the list of Active Part/Part Number that have been inspected by date, default date (today) if the click “Show Active Parts by Date”.


The image shows a modal titled 'Active Parts' with a close button (X) in the top right corner. Below the title is a 'Select Date:' label and a date input field showing '22/12/2025'. Below the date field, there are two entries: 'CRANK AXLE (THH-65/75 S-12)' and 'MC704 STEM (MC416204)'.

17. When user selects part name, and date to generate report. User need press enter or “Download Report”.




The screenshot shows a web application interface for a 'Report Generator'. At the top, there is a 'Back to Dashboard' link. Below it is a blue header with a document icon and the text 'Report Generator'. The form contains two radio buttons: 'Part Check Sheet (Detailed)' (selected) and 'Monthly Summary (All Parts)'. Under 'Select Period', there are three buttons: 'Daily' (selected), 'Weekly', and 'Monthly'. The 'Select Part Name' section has a dropdown menu showing 'MC704 STEM (MC416204)' and a link 'Show Active Parts (By Date)'. The 'Date' field shows '22/12/2025'. A summary bar at the bottom of the form reads 'Part Check Sheet • Daily • 2025-12-22'. A large blue button with a download icon and the text 'Download Report' is at the bottom, highlighted with a red rectangle.

18. Download box will be appear on the right top corner of the browser. (Current shows: Microsoft Edge Browser).




PRODUCTION ACCESS

1. Production can only access “Update JO” button.



2. This is the Update Job Order Page. Users will see at 3 tabs consists of “Update Jo”, “Create New” and “History”. The default page is Update JO tab.



3. If users enter the Part Name, the list of current production jobs will be listed.

The screenshot shows the 'Update Job Order' form. At the top, there are navigation links: 'Back to Dashboard', 'Update JO', 'Create New', and 'History'. The form title is 'Update Job Order' with a 'Production' tab. Below the title is a search bar labeled 'Search Part Name (Active Only)' with a 'Refresh Page' link. The search bar contains 'MC704 STEM (MC416204)'. Below the search bar is a table with 14 rows of production jobs. Each row has a checkbox, 'JO Number', 'Part Name', 'Process', 'Qty', and 'Status'. The 'Status' column shows 'ACTIVE' for all jobs. At the bottom right of the table is a green button labeled 'Mark Selected as Completed'.


☐	JO Number	Part Name	Process	Qty	Status
☐	JO/171125/01328	MC704 STEM (MC416204)	TURNING 3	12000	ACTIVE
☐	JO/171125/01328	MC704 STEM (MC416204)	TURNING 4	12000	ACTIVE
☐	JO/171125/01328	MC704 STEM (MC416204)	MILLING 2	12000	ACTIVE
☐	JO/171125/01328	MC704 STEM (MC416204)	TURNING 2	12000	ACTIVE
☐	JO/171125/01328	MC704 STEM (MC416204)	TURNING 1	12000	ACTIVE
☐	JO/171125/01328	MC704 STEM (MC416204)	TURNING 4	1500	ACTIVE
☐	JO/171125/01328	MC704 STEM (MC416204)	TURNING 3	1500	ACTIVE
☐	JO/171125/01328	MC704 STEM (MC416204)	CUTTING	12000	ACTIVE
☐	JO/171125/01328	MC704 STEM (MC416204)	MILLING 1	12000	ACTIVE
☐	JO/171125/01328	MC704 STEM (MC416204)	STAMPING 3	12000	ACTIVE
☐	JO/171125/01328	MC704 STEM (MC416204)	STAMPING 2	12000	ACTIVE
☐	JO/171125/01328	MC704 STEM (MC416204)	STAMPING 1	12000	ACTIVE

© 2025 Famax Technology (M) System. All rights reserved.

4. To create a new Job Order, users need to choose to create new tab on the top right of the page and field all the required details. Each process needs to be created for each part name and click “Create Job Order”.

The screenshot shows the 'Create Job Order' form. At the top, there are navigation links: 'Back to Dashboard', 'Update JO', 'Create New', and 'History'. The form title is 'Create Job Order'. Below the title are four input fields: 'JO Number' (containing 'Test 123'), 'Quantity' (containing '1500'), 'Part Name' (containing 'Part Name (PartNo123)'), and 'Process' (containing 'Testing Process'). At the bottom of the form is a large blue button labeled 'Create Job Order', which is highlighted with a red rectangle.

5. Click “Confirm” to confirm Job Order creation.




Create Job Order

Create JO: **Test 123** for Part Name (PartNo123)?

This is a confirmation dialog box titled "Create Job Order". It asks the user to confirm the creation of a Job Order (JO) named "Test 123" for the part "Part Name (PartNo123)". There are two buttons at the bottom: "Cancel" and "Confirm". The "Confirm" button is highlighted with a red border.

6. If the job is completely produced, users need to mark the process for the job order to be complete.
 - a. First, select the process using the checkbox.
 - b. Click “Mark Selected as Complete”.



← Back to Dashboard Update JO Create New History

Update Job Order Production

Search Part Name (Active Only) Refresh Page

× Part Name (PartNo123)

☐	JO Number	Part Name	Process	Qty	Status
☒	Test 123	Part Name (PartNo123)	Testing Process	1500	ACTIVE

Mark Selected as Completed

The "Update Job Order" interface shows a table with job order details. The first row is highlighted with a red border, indicating it is selected. The "Mark Selected as Completed" button is also highlighted with a red border.

7. To see the history jobs order, User can go to the History tab in the top right corner of the page. Users can search the page using search field with JO Number and Part Number.

[← Back to Dashboard](#)[Update JO](#)[Create New](#)[History](#)

Job Order History

[Search](#)

Recent History

[Clear / Refresh](#)

JO Number	Part Name	Date Created	Date Completed	Status
JO/051225/01354	AVT 3XA L0200440 (THREAD ROLL)	08/12/2025, 05:37 pm	-	COMPLETED
JO/211125/01337	AVT 3XA L0200440 (THREAD ROLL)	08/12/2025, 05:38 pm	-	COMPLETED
JO/251125/01344	CATHODE / CHOKE COLLAR (SWISS AUTO LATHE MACHINING)	08/12/2025, 08:33 am	-	COMPLETED
JO/081225/01358	DISQUE (K315D.08) (TURNING 1)	15/12/2025, 08:06 am	-	COMPLETED
JO/081225/01358	DISQUE (K315D.08) (TURNING 2)	15/12/2025, 08:07 am	-	COMPLETED
JO/121225/01370	DISQUE (K315D.08) (TURNING 1)	15/12/2025, 08:08 am	-	COMPLETED
JO/121225/01370	DISQUE (K315D.08) (TURNING 2)	15/12/2025, 08:08 am	-	COMPLETED