


Title:

Lenovo L490 Laptop, cellular option is not available:

Summary/Intro:

Although the sim card is inserted into the sim tray, the cellular option is not available. As a result, cannot connect via the sim card

Steps:









Fix:

Go to Device Manager and Enable Fibocom L830-EB



After: Fibocom L830-EB is enabled:





Conclusion (Optional):

In the Bios of the Lenovo L490 Ensure Wireless WAN is enabled, this can be found under Security – I/O Port Access

References (Optional):

Articles/Videos used to prepare guide and additional resources





Created By:

Credit goes to..

Viren Goender