

ROMWBW Errata

Version 3.5

Updated 16 Feb 2024

RetroBrew Computers Group www.retrobrewcomputers.org

Wayne Warthen wwarthen@gmail.com

Contents

1 Errata 1

Chapter 1

Errata

The following errata apply to RomWBW Version 3.5:

- The use of high density floppy disks requires a CPU speed of 8 MHz or greater.
- The PropIO support is based on RomWBW specific firmware. Be sure to program/update your PropIO firmware with the corresponding firmware image provided in the Binary directory of the RomWBW distribution.
- Reading bytes from the video memory of the VDU board (not Color VDU) appears to be problematic. This is only an issue when the driver needs to scroll a portion of the screen which is done by applications such as WordStar or ZDE. You are likely to see screen corruption in this case.