電工實驗(四)

數位實驗(三)步進馬達控制

班級: 電機三乙

組別: 第12組

學號: B103012002

姓名: 林凡皓


一、 程式碼

```
#include "stdio.h"
#include "NuMicro.h"
#include "tmr.h"
#include "system_init.h"
#include "GUI.h"
#include "display.h"
#include "BNCTL.h"
#include "StepMotorAgent.h"
/* define max and mini speed */
#define MaxSpeed 17
#define MinSpeed
 /* global variable define */
uint32_t
uint8_t
              timecount;
               dir;
uint32_t
               speed;
 int main(void)
           // local variable define
          char motor_state_buf[30];
          char SPD_buf[30];
          char direction_buf[30];
uint32_t speedCTL;
          // System initialize
          SYS_Init();
           // button initialize
          BTN_init();
          // Step Motor initialize
          StepMtr_Initial();
          // GUI display initialize
          Display_Init();
          // Init TMR0 for timecount
          TMR0_Initial();
          // Set initial speed and rotate direction
          dir = 1;
          speed = 10;
     while(1)
                     // Scan button
                    BTN_task();
                    // stop rotating
if(Btn_IsOneShot(0x01) == 0x01){
                         GUI_Clear();
                         Btn_OneShotClear(0x01);
                         speed = 0;
```

```
Btn_OneShotClear(0x02);
// speed up rotating
if(Btn_IsOneShot(0x04) == 0x04){
   GUI_Clear();
Btn_OneShotClear(0x04);
    if (speed < MaxSpeed){
    speed ++;      // only speed up when the speed does not exceed the maximum speed</pre>
// speed down rotating
if(Btn_IsOneShot(0x08) == 0x08){
    GUI_Clear();
   Btn_OneShotClear(0x08);
   if (speed == 0){
       speed =1;
    else if (speed > MinSpeed){
       speed --; // only speed down when the speed is larger than minimum speed
// Step motor output
speedCTL = 1000/speed;
else
   speedCTL = 0;
StepMtr_Task(dir, speedCTL);
sprintf(SPD_buf,"speed : %02d rpm" , speed*6); //6~102
// Display current state
if (speed == 0)
   Display_buf("motor state : Stopped", 1, 1); // display "motor state : Stopped" when not rotating
   Display_buf("motor state : Running", 1, 1); // display "motor state : Running" when rotating
Display_buf(SPD_buf, 1, 25);
// Display rotate direction
if (dir)
   Display_buf("direction : Clockwise", 1, 49);
   Display_buf("direction : CounterClockwise", 1, 49);
```

}

二、 流程圖



三、 心得

這次實驗與上學期的步進馬達控制實驗有點類似,上學期是使用 dip swich 來控制馬達的轉速與方向,這學期則改為使用按鍵來控制。這兩次實驗有幾個不同,第一個為實現方式,上學期是透過寫 verilog 來做硬體的實現,這學期則是寫 C 來做嵌入式的實現。第二個為速度控制,上學期是透過修改除頻器的頻率來控制轉速,這學期則是直接透過變數 speed 來控制。經過這次的實驗與上學期實驗的比較,可以學到嵌入式系統與數位硬體的差異,此外,也透過這次實驗的練習讓我們更加了解如何建立專案以及 C 語言的語法。